



Rig drills into salt mine

The lake then drained into the hole, expanding the size of that hole as the soil and salt were washed into the mine by the rushing water, ...

Best Practices and Guidelines for Drilling Through Salt Formation In drilling operations involving salt formations, several key considerations need to be ...

The rig crew had been drilling a test well into deposits alongside a salt dome under Lake Peigneur. By some miscalculation, the assembly drilled ...

An exploratory drilling exercise miscalculates the location of a salt mine while drilling through a lake bed. The mine is hit, and the oil derrick, the mine, the lake, and a few barges...

On the morning of November 21, 1980, a Texaco oil drill bit on Louisiana's Lake Peigneur struck a salt mine beneath the water. And then...

Drilling disaster The backwards flow of the normally outflowing Delcambre Canal temporarily created the biggest waterfall in Louisiana. On November 20, 1980, an oil rig contracted by ...

The Jefferson Island Mine, owned and operated by the Diamond Crystal Salt Co., was flooded in 1980 due to a drilling accident by Texaco that swallowed the rig and closed the ...

Have you ever heard of Louisiana's Vanished Lake? This mysterious body of water, known as Lake Peigneur, disappeared in a single day back in 1980. Imagine a lake ...

On Nov. 20, 1980, the Jefferson Island salt mines were destroyed when a funnel was accidentally created at the bottom of the lake--sweeping up everything ...

He was Captain of Louisiana State Police Troop-I when a miscalculation sent an oil rig's drill directly into the salt mine instead of under ...

Before your eyes, an entire drilling rig, barges, and acres of land vanish in a swirling vortex, sucked into the earth as if pulled by an invisible hand. This isn't a scene from a ...

As the canal refilled the crater over the next two days, nine of the sunken barges popped back to the surface like corks, though the drilling rigs ...

The Jefferson Island dome is the location of Lake Peigneur, which grew substantially during a 1980 incident



Rig drills into salt mine

where an underground salt mine, active at ...

An oil rig platform drilling into Lake Peigneur in Louisiana accidentally sets off a chain of events that would eventually turn the ...

The Lake Peigneur drilling disaster is unbelievable! That catastrophic man-made event drained an entire lake, swallowed up eleven barges, many trees and 65 acres (260,000 m²) of land into a salt mine shaft, creating the biggest waterfall of Louisiana. The Lake Peigneur ...

How do you turn a ten-foot deep freshwater lake into a saltwater one over a thousand feet deep? The residents of Lake Peigneur in Louisiana found out on 20 November ...

At the same time the oil workers were watching their \$5 million drilling rig disappear into the lake, workers in the salt mines below the lake noticed something was wrong as well; a ...

It seems their drill had accidentally penetrated a main shaft of the Diamond Crystal salt mine, whose tunnels crisscrossed the rock under the ...

Find out a comprehensive guide to salt mining, including techniques and technologies. Choose drilling rigs, workover rigs and maintenance services ...

Despite the fact that the mine was rapidly filling with water and the exit elevator could only take up eight people at a time, all 55 miners were ...

On the morning of November 21 1980, a TEXACO Oil Rig team was drilling and noticed that their drill had seized up. The following video shows what 1 mistake can cost an entire project and more. You ...

The Jefferson Island Mine, owned and operated by the Diamond Crystal Salt Co., was flooded in 1980 due to a drilling accident by Texaco that ...

An oil drilling operation at Lake Peigneur accidentally punctured a salt dome, creating a sinkhole that swallowed barges and caused the Delcambre Canal ...

The Jefferson Island Salt Dome is the location of Lake Peigneur, which grew substantially during a 1980 incident where an underground salt mine, active at ...

A mining crew drilled through the bottom of a lake and into a salt mine. As the lake begins to drain into the mine, a whirlpool forms, sucking down barges, kilometers of land and ...

This video from the History Channel shows how Lake Peigneur in Louisiana disappeared in 1980 when the location of a salt mine was miscalculated during exploratory oil ...



Rig drills into salt mine

At that time, Diamond Crystal Salt Company operated the Jefferson Island salt mine under the lake, while a Texaco oil rig was drilling down from the surface of the lake searching for petroleum ...

Louisiana's salt deposits are in "salt domes" -- columns that rise for miles (kilometers) from larger deposits deep underground, emerging like islands in surrounding ...

Texaco had accidentally drilled into one of those shafts. Water dissolves salt, explaining the formation of the massive crater as water poured from the lake into the mine. Fortunately, the ...

Web: <https://kwa-andries.co.za>