



## Cactus drilling rig tornado damage

Telescopic Crane Drilling Rig Mumbai Maharashtra For Sale Quick Saves Liebherr - LTM 1080-1, 80 Tons Crane For Sale and Hire in Mumbai, ...

On 24 May 2011, Cactus Rig 117, operating near Calumet, Okla., suffered a direct hit by an F5 tornado that resulted in an estimated \$14 million in damage. Not a ...

Oklahoma City-based Cactus Drilling Co. LLC credits its reinforced safe room for helping 13 employees and contractors survive a direct ...

Three Weatherford contractors were injured when a tornado struck the drilling rig they were working on late yesterday afternoon near Canadian. The three men were working ...

Carl Wilkerson Jr., a Motorhand on Rig 154 currently drilling near McAlester, OK, has been employed with Cactus since November 2006. He has been a volunteer firefighter ...

The many damage feats caused and the behavior of this event are both historic. In this summary, we cover every aspect of the maelstrom in as much detail as possible and bring ...

He said the rig, owned by Oklahoma City 's Cactus Drilling Co., was evacuated before the tornado hit. In the aftermath of the storm, Devon has shut production at some of its ...

Learn more about how Cactus Drilling utilizes the latest technology to make every operation safe and efficient for the benefit of all involved.

IMO, quite possibly the most violent tornado in a year absolutely packed with historically violent tornadoes. You're sort of splitting hairs when you get to that level of ...

Community Services Director Terry Floyd also said Tuesday that the storm did extensive damage to the rig, as well as a Devon Energy ...

Damage at the Cactus 117 oil drilling rig near El Reno, showing the mangled and overturned rig On May 24, 2011, a long-track and extremely powerful tornado ...

This is the first portion of a two-part series focusing on the Calumet-El Reno-Piedmont-Guthrie, OK, tornado of May 24, 2011. The summary covers the track from its ...

Reply reply AngriestManinWestTX o Even more impressive is that everyone survived on the rig because



## Cactus drilling rig tornado damage

Cactus Drilling had anchored rooms for the crew ...

**INTRODUCTION** On 24 May 2011 a total of 22 tornadoes struck central Oklahoma (Fig. 1). Fortunately, these tornadoes missed towns and metropolitan areas. The next day, the ...

**Careers** Are you interested in becoming part of a team that does challenging and important work while achieving rewarding results? Cactus may well be the career home you're searching for. ...

This tornado was over a mile wide at its max intensity and had recorded max wind speeds of 295 mph (the 3rd highest wind speeds ever recorded on earth). Notable damage from this tornado ...

This tornado was over a mile wide at its max intensity and had recorded max wind speeds of 295 mph (the 3rd highest wind speeds ever recorded on earth). ...

The original shelter was designed after a tornado hit a Texas location in 2009. Since most of the company's Oklahoma and Texas rigs were in the tornado belt, Cactus believed something ...

The storm destroyed a drilling rig being operated nearby by Denver-based Cimarex Energy Co. Devon officials are assessing the damage to the \$140 million plant, but ...

Cactus Drilling ultimately spent around \$500,000 to anchor its rig change houses to withstand an F5 tornado. In 2011, a Cactus rig in Oklahoma ...

**Rig Fleet** Our high-spec, fit-for-purpose rigs are equipped with the technology, capacities and capabilities required to tackle today's most complex drilling ...

**Damage at the Cactus 117 oil drilling rig near El Reno, showing the mangled and overturned rig** On May 24, 2011, a long-track and extremely powerful tornado struck the areas near or within ...

Anyways, here's some absolutely incredible damage photos from the Cactus 117 Oil Rig where the tornado likely hit maximum intensity. This is easily some of the most violent and ...

Community Services Director Terry Floyd also said Tuesday that the storm did extensive damage to the rig, as well as a Devon Energy production plant and a metal business. Floyd said he ...

A BOE contributor sent pictures of Cactus Rig 117, which was destroyed by a tornado on May 24, 2011, near Calumet, Oklahoma. The F5 ...



## Cactus drilling rig tornado damage

Web: <https://kwa-andries.co.za>