



Chicago drill rig collapse

An oil rig owned and operated by Well Services Petroleum Company Limited has collapsed in waters off Trinidad's south-west peninsular. ...

A drill-head crane collapse outside the Bryn Mawr Avenue Red Line station stopped trains, damaged power lines, and also forced the evacuation of a nearby bui...

In the early hours of December 22 local time, a jack-up drilling rig collapsed in the waters of the Republic of Trinidad and Tobago (a small country located in the southern ...

A drill-head crane collapse outside the Bryn Mawr Avenue Red Line station stopped trains, damaged power lines, and also forced the evacuation of a ...

CHICAGO -- A drill rig collapsed at the Bryn Mawr Red Line station in Edgewater Wednesday evening, temporarily halting CTA service, local ...

The drill rig operated by a private contractor toppled over in the 1100 block of West Bryn Mawr Avenue in the Edgewater neighborhood, knocking ...

A drill rig collapse at the Sehit Aybuke Yalcin in Türkiye's Sirnak oil exploration site on Gabar Mountain has injured three individuals, according to ...

Workers rescued as rig collapses Sascha Wilson December 22, 2024 SASCHA WILSON Senior Reporter Scores of workers had to be rescued overnight after a privately ...

CHICAGO (CBS) -- A drill-head crane collapse outside the Bryn Mawr Avenue Red Line station stopped trains, damaged power lines, and also forced the evacuation of a nearby ...

Jacobsen Construction has offered updated information on the equipment failure Tuesday night that caused the collapse of a drill rig.

En­er­gy and En­er­gy In­dus­tries Min­is­ter Stu­art Young is con­firm­ing that state owned oil and gas com­pa­ny Her­itage Pe­tro­le­um Com­pa­ny Ltd is pro­vid­ing ...

Chicago Drilling Company is a geotechnical drilling contractor offering soil boring services nationwide for all types of construction projects. This includes phase 2, site exploration, ...



Chicago drill rig collapse

Photos from @ Cfdmedia Crane Collapse Yesterday Afternoon Amazing NO Injuries! That's a Miracle
*Chicago | Still and Box Alarm | Collapse Rescue | 1119 W Bryn ...

On Sunday, a jackup rig partially collapsed off the coast of Trinidad, injuring one worker and leaving one missing. At about 0300 hours on ...

A drill rig at a construction site collapsed onto cars on State Street in downtown Salt Lake. The operator sustained injuries. The collapse ...

Drill Rig Collapses at Chicago Transit Authority Red/Purple Line Site, No Injuries Reported CTA service briefly halted, Walsh-Fluor team works to remove collapsed equipment from alleyway

Pete Phillip, a worker attached to Well Services Limited, is missing after an incident at Rig 110 within the Heritage Offshore East Field of Trinidad and Tobago on Sunday ...

Before daybreak on Sunday, part of the oil drilling rig collapsed, injuring one man. A second worker, Pete Phillip, is unaccounted for.

Seplat Energy on Tuesday announced that one person died and three others were missing as its drilling rig collapsed in Delta State. Roger ...

Search on for missing man after rig collapse A search and rescue effort is now underway after an offshore drilling rig collapse in the early hours ...

PART of a drilling rig - the derrick - owned by Well Services Petroleum Company Ltd, a private company, collapsed into the sea early on the morning of December 22, sending ...

Vladimir Putin has suffered another dramatic blow after a drilling rig collapsed and burst into flames in Siberia, leaving three workers in critical ...

A 100-ton hydraulic drill rig tipped over onto the street at the site of the Chicago Transit Authority's \$2.1-billion Red/Purple line project. No injuries were reported and the cause of the incident is ...

Crews are still working to remove the massive construction crane and figure out what caused this collapse. It crushed cars and caused an ...

The Howard County Sheriff's Office identifies the man as 40-year-old Felipe Saiz of Big Spring. Investigators say the victim was dead at the scene near Big Spring.

CHICAGO -- Rush hour on the North Side was more chaotic than usual Wednesday after a drill head crane toppled over near a Red Line platform, causing CTA service to slow ...



Chicago drill rig collapse

A crane collapse brought a pair of Chicago Transit Authority train lines (the Chicago L) to a dead stop and forced the evacuation of a nearby residential building.

Web: <https://kwa-andries.co.za>