



# Drilling rig accident reports

Abstract: Employees #1 through #5 were crew members on a barge-mounted drilling rig in the Atchafalaya Basin off southern Louisiana.

When someone has been injured or killed in a motor-vehicle collision in Virginia, the accident victim and their family members are left with medical bills, lost income, and other costs.

[Return to Accident Search Results](#) [Accident Report Detail](#) [Accident Summary](#) Nr: 200643518 - One Employee Is Killed and Two Are Injured at Drilling Rig ... Abstract: On July 6, 2006, ...

Alexander L. Kielland, an accommodation rig being attached to a drilling platform, capsized on 27th March 1980 on the Ekofisk field in the North Sea. During stormy weather, one of the five ...

On April 20, 2010, a sudden explosion and fire occurred on the oil rig. The accident resulted in the deaths of 11 workers and caused a massive, ongoing oil spill into the Gulf of Mexico.

Additional relevant information including key findings appears in subsequent volumes. This chapter summarizes information on the companies and entities involved in the drilling and ...

IADC's Incident Statistics Program (ISP) recently released the Q1 2024 Summary Report of occupational incidents for drilling contractors ...

Oil and gas industry accidents have left indelible marks on history, causing immense human loss, environmental devastation, and financial damage.

[Fatality Reports](#) [File a Complaint](#) [Publications](#) [Safety and Health Topics](#) [Pages](#) [Videos](#) [Compliance Assistance](#) [Compliance Assistance Specialists](#) [Consultation Services](#) ...

To perform a preliminary survey on the sources of information, databases, etc. existing at national, international and open market level, and the availability of these information sources to the ...

**INVESTIGATION REPORT EXECUTIVE SUMMARY DRILLING RIG EXPLOSION AND FIRE AT THE MACONDO WELL (11 Fatalities, 17 Injured, and Serious Environmental ...**

**Deepwater Horizon Accident Investigation Report** This is British Petroleum's (BP) internal investigative report of and about the Deepwater Horizon explosion, subsequent loss of ...

Abstract: At 1:30 a.m. on April 13, 2021, an employee was working 30 feet below ground on a Precision



## Drilling rig accident reports

Drilling Rig floor running intermediate casing into the well by connecting each length ...

5 days ago&#0183; MSHA investigates each mining fatality and prepares the following documents to alert the mining community and prevent similar occurrences. ...

The semi-submersible "flotel" (floating hotel) Alexander L. Kielland capsized on 27 March 1980 while bridge connected to the steel jacket Ekofisk Edda platform. The flotel lost one of its five legs in severe gale force winds, but not an extreme storm. The accident started with ...

The BP investigation team began its work immediately in the aftermath of the accident, working independently from other BP spill response activities and organizations. The ability to gather ...

The rig's owner said no one could have predicted it. "This unforeseen accident," Robert Blackford, the president of Wolverine Drilling, wrote in a letter to OSHA two months ...

Authorities Investigating Oklahoma Rig Explosion, Deadliest U.S. Drilling Accident In Years Federal and state authorities are investigating the cause of the ...

The drill crew was in the process of running marine riser for Well PS001, when a 25 pound riser bolt insert dislodged out of the riser flange and fell approximately 75 feet to the ...

Chemical Safety Board Says Deadliest Drilling Accident in a Decade Was Preventable Federal safety regulators, state oil and gas authorities, and the energy industry ...

The drilling contractor, in this case Patterson-UTI Drilling Company, LLC (Patterson-UTI), brings the infrastructure (drilling rig) and supplies the workforce (rig crew) ...

The BSEE Investigation consisted of reviewing electronic and written material, including but not limited to bridging documents, International Association of Drilling Contractor ...

Advancing the Drilling IndustryIADC recently published the Incident Statistics Program (ISP) 2023 Annual Report, which provides a summary of ...

Abstract: On July 6, 2006, Employees #1, #2, and #3 were drilling an oil and gas well. They were preparing to insert a 30-foot section of drilling pipe into the nearly 6,500-foot-long drilling string.

While action has been taken to minimise the risks of accidents on offshore installations and improve the safety of offshore oil and gas ...

Since 1962, the IADC Incident Statistics Program (ISP) has tracked safety and accident information for the drilling industry. To record data reflecting accident ...



## Drilling rig accident reports

On August 13, 2020, an incident occurred on the Helmerich & Payne (H& P) 100 platform rig while under contract for Talos Oil and Gas LLC. The H& P 100, operating on Talos" production ...

RigReports improves Drilling, Completions, Workovers and Facility Reports. Well Lifecycle Reporting & Analytics, Cloud-based SaaS software application for ...

Offshore workers are susceptible to an exponentially long list of risks associated with their work. If you or a loved one have been injured in an ...

Web: <https://kwa-andries.co.za>