



Patterson drilling rig 219 explosion

QUINTON, Okla. - Attorneys for the family of a man killed in a drilling rig explosion say the operator of the oil well was trying to save money ...

It was the deadliest drilling accident in the United States since the Deepwater Horizon rig exploded in the Gulf of Mexico in 2010, killing 11 workers.

Patterson-UTI Drilling Co. was the drilling contractor hired by RMO. The Patterson rig 219 had drilled both wells. Authorities say there were 22 workers on the well site, which ...

The well head burned around the Patterson Rig No. 219 for hours Monday, until the well head could be shut off. Officials said the remote switch for a safety valve for the well -- a ...

The US Chemical Safety Board is in the early stages of its investigation into the fatal gas well explosion near Quinton, Oklahoma. Since arriving on scene on January 24, the ...

A training video for the onshore drilling industry detailing lessons learned from the January 22, 2018, blowout and fire at the Pryor Trust gas well in Pittsburg County, Oklahoma, that fatally ...

The driller involved in the deadly Oklahoma rig explosion has a history of fatal accidents by Sean Murphy, Associated Press, January 25, 2018, Pittsburgh Post-Gazette ...

Chemical safety board officials said massive mud gains were a "strong indication" of gas influx leading to the Patterson 219 rig explosion this year.

Five workers died -- three employed by drilling company Patterson-UTI Energy -- 17 others were able to evacuate the well site; one worker was flown to a Tulsa hospital for ...

On January 22, 2018, the Patterson 219 drilling rig near Quinton, Oklahoma exploded after an uncontrolled release of gas during the drilling process. Five workers died in ...

The U.S. Chemical Safety and Hazard Investigation Board or CSB, presented the final report on the deadly rig explosion near Quinton last year that killed five workers.

A new lawsuit by the family of Peter Waldrige, who died along with four others in January's deadly Oklahoma gas explosion, alleges Patterson-UTI Drilling ignored important safety warnings.

The gas rig, known as Patterson 219, was located near Quinton, Oklahoma, about 100 miles southeast of



Patterson drilling rig 219 explosion

Tulsa, and was reportedly jointly ...

Federal and state authorities are investigating the cause of the deadly explosion and fire at a natural gas drilling rig in southeastern ...

The explosion and fire happened eleven days after Rig 219 had been moved to the well site near the town of Quinton. The blowout happened the morning of January 22, 2018.

Last January, five oil workers were killed in a fire and explosion at a Quinton, Oklahoma drilling rig. This was the deadliest drilling accident in the U.S. since 2010, when 11 ...

Another sign there was about to be a problem, the investigation shows, is that a Patterson-UTI crew member observed mud flowing out of the ...

Patterson's Rig 219 burned for eight hours Jan. 22, 2018, after an explosion at an oil well site near Quinton, about 100 miles southeast of Tulsa. ...

Several people are missing after an explosion ripped through an Oklahoma drilling rig Monday. CBS News correspondent DeMarco Morgan has the latest bscribe ...

Patterson-UTI Energy Inc.'s Rig 219 was damaged in a 2018 fire near Quinton, Okla., that killed five men. Well operator Red Mountain Energy ...

Drilling rig alarms were disabled by the workers prior to explosion and fire, which swept through the drilling rig, according to the report.

The families of all victims that included Oklahomans Parker Waldrige of Crescent, Matt Smith of McAlester and Roger Cunningham of Seminole previously reached settlements ...

OKLAHOMA CITY (AP) -- Ten workers have died over the past decade at well sites linked to drilling contractor Patterson-UTI, the same driller involved in this week's rig ...

Once the initial burp subsided, another burp occurred and gas fumes found an ignition source, causing a series of explosions on and around the rig. Five employees were in ...

Attorneys filed a lawsuit against the drilling companies involved in the Patterson 219 rig explosion, seeking more than \$75,000 in damages for the wife of one of the five men killed. ...

The explosion occurred at the Patterson 219 gas drilling rig near Quinton, Oklahoma, after crews had drilled about 13,500 feet. The explosion was caused by an ...



Patterson drilling rig 219 explosion

The drilling contractor, in this case Patterson-UTI Drilling Company, LLC (Patterson-UTI), brings the infrastructure (drilling rig) and supplies the ...

Patterson-UTI has about 25 drilling rigs active in Oklahoma, second only to Texas, where it has nearly 60 rigs in operation. Two investigators from the Chemical Safety Board ...

Accident Report Detail Accident Summary Nr: 102594.015 - Employee is killed in explosion on oil rig ...
Abstract: At 8:37 a.m. on January 22, 2018, one employee was working ...

"This was the deadliest U.S. drilling accident since the 2010 deep-water horizon rig explosion which killed 11 workers," said U.S. Chemical ...

The bodies of five workers, including one Texan, were recovered Tuesday after an explosion ripped through a drilling rig in Oklahoma, ...

Web: <https://kwa-andries.co.za>